



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
May 19, 2008

Supervisor LR

<b>Mine Name:</b> Rhyolite1	<b>Permit Number:</b> S210032
<b>Operator Name:</b> Color County Rock LLC	<b>Inspection Date:</b> April 23, 2008
<b>Inspector(s):</b> Tom Munson	<b>Time:</b> 1:30-2:30 PM
<b>Other Participants:</b> none	<b>Mine Status:</b> Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

To visit the site and determine on the ground disturbance.

**Inspection Summary:**

A small pit and various stockpiles of crushed material was observed. No one was on site and the disturbance is permitted for 3 acres and bonded for \$15,000 dollars. The site and the access road was GPS'ed at 2.1 acres.

Photos were taken to document site conditions.

**Conclusions and Recommendations:**

Continue to monitor this site when in the area.

**Inspector's Signature**

TM:pb

cc: (OPERATOR)

Ed\_ginouves@blm.gov

O:\M021-Iron\S0210032-RhyoliteQuarry\inspections\04232008insp.doc

080001